

MTN-020 LC:

HIV Testing Case Study and Study Closeout

Edward Livant BS, MPH MTN Laboratory Center

HIV Case Study

- A clinical research site had some irregular HIV testing results.
- Additional Testing was performed at the MTN Virology Core which revealed some false negative testing results (shown on next Slide).
- This triggered an LC site visit.

Study Visit	Site Testing Result	LC Virology Laboratory Result
Month 16	Unigold Negative, Determine Negative	Unigold Positive, HIV RNA = 912 copies/ml
Month 17	Missed Visit	
Month 18	Unigold Positive, Determine Positive	NA

Site Practice	Package Insert Direction	Major Concern	
Deviation 1: Technician added 2 drops of wash solution	Add 4 drops of wash solution	2 drops of wash may be enough to make the internal control line become positive while	
		not moving the patient sample into the test area.	
Deviation 2: Technician used cold wash solution directly from refrigerator	Allow wash solution to come to room temperature for 20 minutes before use	Cold reagent will slow down the test reaction.	

Observati on #	Sample	Drops Wash Solution Added	Wash Solution Temperature	Result 10-12 Minutes (Valid Read Time)	Result Change Post 12 Minutes (Post Valid Read Time)
1	Positive Control	4	Room Temp	Positive	NA
2	Positive Control	4	Cold	Positive	NA
3	Positive Control	2	Room Temp	Positive	NA
4	Positive Control	2	Cold	Positive	NA

Observati on #	Sample	Drops Wash Solution Added	Wash Solution Temperature	Result 10-12 Minutes (Valid Read Time)	Result Change Post 12 Minutes (Post Valid Read Time)
5	Participant	4	Room Temp	Positive	NA
6	Participant	4	Cold	False Negative	Positive between 12- 13 minutes
7	Participant	2	Room Temp	False Negative	No change at 15 minutes
8	Participant	2	Cold	False Negative	Positive at 13 minutes

HIV Case Study-Conclusions

- EQA and QC can be 100% successful even while test procedural errors are occurring.
- Procedural errors greatly increase the risk of false negative results in early seroconversion samples or other samples with low antibody titers
- Package insert directions must be followed carefully to maximize performance.